


Lithium-Ion Battery Fire Investigations

August 2026



Year to date, there have been 40 fires investigated, where a lithium-ion battery was found in the area of origin. Micro Mobility make up the highest number of incidents year-to-date.

Type of Device Powered



Name of Product:

OCOOPA

Hazard:

The lithium-ion battery in the recalled hand warmers can overheat and ignite, posing a risk of serious injury or death from fire and burn hazards.

Remedy:

Consumers should immediately stop using

Recall Date:

July 30, 2026


Units:

About 1.5 Million

U.S. Consumer Product Safety Commission



Structure Type



FIRES AND EMERGENCIES



If a battery overheats or you notice an odor, change in shape/color, leaking, or odd noises from a device, stop using immediately. If safe to do so, move the device away from anything that can catch fire and call 911.



Lithium-Ion batteries are known to unexpectedly re-ignite minutes, hours, and even days after all visible fire has been put out.



If you observe a lithium-ion battery fire, leave the area, CLOSE the door, and call 911 immediately.



Water and fire extinguishers do not work on lithium-ion battery fires.

Source: Connecticut Vision Zero